



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 28, 2008

Reviewed 

Mine Name: Ultradent O C Claims	Permit Number: S0450057
Operator Name: Ultradent Products	Inspection Date: May 14, 2008
Inspector(s): L Heppler	Time: 12:30pm
Other Participants: None	Mine Status: INS

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: None listed **Bond Amount:** \$ None listed. **Permit Fee** is delinquent – need to pay fee by June 30, 2008 or reclaim ground.


Purpose of Inspection: Routine annual Inspection

Inspection Summary: Data base indicates this site has been active in previous years but never been inspected. See map for access. No signs of recent activity. Trailer with satellite dish and fenced area are on site. Open portal and pad area are less than 1 acre. Open Portal is a safety hazard. Every effort should be made to salvage top soil from the site prior to mining. No topsoil stockpile were noted on site. There has been no reclamation or regrading started on the site. There is trash that needs to be removed from the site.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator has 30 days to comply with all local, state and federal rules, including, but not limited to the unsafe portal and rockfall hazard at the portal opening. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature



LAH:pb

cc: Peter Allred

Larry Garahana – BLM, Will Stokes - SITLA)

Attach - GIS

File Name and Path

Inspection Date: May 14, 2008
Page 2 of 2
S/047/0057

Photos Taken 05-14-08

